



on Fire and Building Safety in Bangladesh

SAFETY NOTIFICATION TO WORKERS IN KENTO ASIA LTD.

(Address: Plot # B-32, BSCIC Industrial Estate, Tongi, Gazipur)

Date: 8th September 2016

The Accord is a legal agreement between international garment brands and unions that represent workers. The purpose of the Accord is to protect the safety of garment workers by inspecting factory buildings, identifying risks to worker safety, and making sure that factory owners eliminate these risks by renovating and repairing the buildings.

The Accord has conducted an inspection of Kento Asia Ltd. on 15 May, 2014 and found a number of problems that could cause serious harm to workers. The Accord has asked Kento Asia Ltd. to make changes to eliminate these risks. Unfortunately, Kento Asia Ltd. has failed to:

- Remove locking features or rendered inoperable from the egress doors/gates. This could result in workers be locked in the factory during a fire or another emergency.
- Remove collapsible gates/sliding door/rolling shutters. This could be an obstacle for workers during evacuation in case of fire incident or another emergency.
- Install fire doors. This could result in workers becoming stuck on the higher floors of the building if there is a fire.
- Install a fire alarm system. This could result in workers not being warned that there is a fire.
- Install a fire sprinkler system. This could result in not discharging water when there is a fire incident.
- Complete fire separation in the relevant areas. This could result in workers becoming stuck on the higher floors of the building if there is a fire.
- Submit a detailed analysis of the structural safety of the building and fix any problems with the building structure. This could result in the failure of the structure and injuries to workers.
- Safely install and maintain electrical equipment and fix up electrical wiring. This could create serious electrical hazard at any moment in the factory which might lead to fire incidents.

The Accord has made many efforts to get the owners of Kento Asia Ltd. to fix these safety hazards, so that workers will be safe, but the owners have refused to do so.

As a result, Kento Asia Ltd. is unsafe for workers. Because of this, the brands that have signed the Accord will no longer do business with Kento Asia Ltd. and will no longer place any orders at the factory. The Accord wants to make sure that all workers at Kento Asia Ltd. are aware that the building is not safe.

If workers choose not to work at Kento Asia Ltd. because of these safety risks, or if Kento Asia Ltd. closes, the brands that have signed the Accord will make an effort to help workers find jobs at nearby factories that are safe. There is no guarantee that a job will be available, but the brands will try to assist.

For information, workers can contact:

The Accord:

- Mr. Rob Wayss Mobile No. 01755-583744
- Mr. Brad Loewen Mobile No. 01781-900956

The Industriall Bangladesh Council:

- Mr. Roy Ramesh Chandra Mobile No. 01819-223014
- Mr. Amirul Haque Amin Mobile No. 01731-201302
- Mr. Kutubuddin Ahmed Mobile No. 01711-047688

Also, the government of Bangladesh has established a helpline for RMG workers at: 0800-4455000. There is no charge for calling this number.

STICHTING BANGLADESH ACCORD FOUNDATION

The Accord on Building and Fire Safety in Bangladesh

STICHTING BANGLADESH ACCORD FOUNDATION	Level 13, AJ Heights Cha 72/1/d, Pragati Sarani North Badda, Dhaka - 1212 Bangladesh	Tel +88 02 9852093-6 Tel +88 01766695900	Keizersgracht 62-64 1015 CS Amsterdam The Netherlands Tel +31 (0)20 5207431	contact@bangladeshaccord.com www.bangladeshaccord.org
---	---	---	--	--